

Sets, Kits, and Outfits, Components List for Tool Kit, Pipefitters Supplementary

SC: 5180-95-N42
NSN: 5180-00-596-1509
LIN: W48759

System Description

Kit contains the necessary components and hand tools required for intended use by pipefitters.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil